[4910-13-U]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39 7-27011-3

[Docket No. FAA-2006-+++++; Directorate Identifier 2006-NM-175-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A318, A319, A320, and A321 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

that applies to all Airbus Model A318, A319, A320, and A321 airplanes. The existing AD currently requires inspecting to determine the part number and serial number of the fuel tank boost pumps and, for airplanes with affected pumps, revising the Airplane Flight Manual (AFM) and the FAA-approved maintenance program. The existing AD also provides for optional terminating action for compliance with the revisions to the AFM and the maintenance program. This proposed AD would require modifying the fuel tank boost pumps, which would allow removal of the limitations from the AFM and the maintenance program. This proposed AD results from a report that a fuel tank boost pump failed in service, due to a detached screw of the boost pump housing that created short circuit between the stator and rotor of the boost pump motor and tripped a circuit breaker. We are proposing this AD to prevent electrical arcing in the fuel tank boost pump motor, which, in the presence of a combustible air-fuel mixture in the pump, could result in an explosion and loss of the airplane.

DATES: We must receive comments on this proposed AD by [insert date 30 days after date of publication in the FEDERAL REGISTER].

	CONCURRENCES
	POUTING SYMBOL ANNIE TD N
	INITIALS/SIGNATURE
	Man
	DATE 1/3/0C
	BOB ANMICE
	INITIALSSIGNATURE
	DATE
	ROUTING SYMBOL
	AEG
	INITIALS/SIGNATURE
	DATE
	11/9/06
D	POUTING SYMBOL
5	INITIALS/SIGNATURE
-	CC
e	12/26/01
	ROUTING SYMBOL
	INITIALS/SIGNATURE
)	29
	DATE 1/2/06
ے fi	ROUTING SYMBOL
11	-10/
16	INITIALS SIGNATURE
	DATE
	ROUTING SYMBOL
þ	a -100
t	INITIALS/SIGNATURE
	DATE
	11/2/01
u	BOUTING SYMBOL O
1	